

Work Order ID' 54488

December 10, 2009 9:01:48 AM



Page 1

Item ID: D412-724-043

Accept:



Setup Start



Revision ID:

Stop



Item Name: Head Rest Assembly, LH

Start Date: 12/10/09 Start Qty: 1.00



Cust Item ID:

Required Date: 12/11/09 Req'd Qty: 1.00



Customer:

Reference:

Approvals: Process Plan:

Date:

Tooling:

Date:

Run Start



QC:

Date:

SPC (Y/N):

Date:

Stop



Sequence ID/
Work Center ID

Operation
Description

Set Up/
Run Hours

Draw
Number

Draw
Rev.

Plan
Code

Accept
Qty

Reject
Qty

Reject
Number

Insp.
Stamp

Draw Nbr

Revision Nbr

N/A

Rev N/A

100

0.00



DOCUMENT CONTROL

DC

Memo

0.00

Document Control

If D412-724-043 is a W/O on it's own, Photocopy bluefile and create labels per
PPP D412-724-043 CHG001

N/A (54486)

110

Pick Kit

0.00



Packaging

Memo

0.00

Packaging

9/12/14 SP

120

QC4- 100% Inspect kits for completeness

0.00



QC

Memo

0.00

Quality Control

→ S 02/12/15

⊙ /

Work Order ID' 54488

December 10, 2009 9:01:48 AM



Page 2

Item ID: D412-724-043

Accept



Setup Start



Revision ID:

Stop



Item Name: Head Rest Assembly, LH

Start Date: 12/10/09 Start Qty: 1.00



Cust Item ID:

Required Date: 12/11/09 Req'd Qty: 1.00



Customer:

Reference:

Run Start



Approvals: Process Plan:

Date:

Tooling:

Date:

Stop



QC:

Date:

SPC (Y/N):

Date:

Sequence ID/
Work Center ID

Operation
Description

Set Up/
Run Hours

Draw
Number

Draw
Rev.

Plan
Code

Accept
Qty

Reject
Qty

Reject
Number

Insp.
Stamp

130

0.00



Packaging

Packaging

Memo

0.00

Identify and pack for shipping as per PPP D412-724-0431 Location: _____ :PPP Rev: _____

APP. 54488 9/12/15 SP (R)

140

QC21- Final Inspection - Work Order Release

0.00



QC

Memo

0.00

Quality Control

09.12.15

09.12.15

Picklist Print

December 10, 2009 9:01:47 AM

Page 1

Work Order ID: 54488

Parent Item: D412-724-043

Parent Item Name: Head Rest Assembly, LH

Comments:

Start Date: 12/10/09

Required Date: 12/11/09

Start Qty: 1.00

Required Qty: 1.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
AN525-10R6 Screw		Purchased	No			120	Each	110.0000	4.0000		12/10/14	sl

Warehouse Loc Qty Loc Code
Location

Main Warehouse

ST

110

101203

110

Manufactured No

120

Each

3.0000

1.0000

4
B54629 12/10/10

Warehouse Loc Qty Loc Code
Location

Main Warehouse

ST

3

44448

3

Manufactured No

120

Each

13.0000

1.0000

9/12/14 sl

D3304-043

Tube Assembly

Warehouse Loc Qty Loc Code
Location

Main Warehouse

ST

13

42172

5

44355

8

25.3 WEIGHT AND BALANCE

There is negligible weight change associated with the installation of the Dart Head Rest.

25.4 PARTS LIST

QTY -011	QTY -041	QTY -043	QTY -044	Part Number	Description
X				D412-724-011	Dart Head Rest Kit, for 205/212/412
2	X			D412-724-041	Head Rest Assembly, Center
1		X		D412-724-043	Head Rest Assembly, LH
1			X	D412-724-044	Head Rest Assembly, RH
	1	1	1	D3303-041	Head Rest
	1			D3304-041	Tube Assembly
		1		D3304-043	Tube Assembly
			1	D3304-044	Tube Assembly
	4	4	4	AN525-10R6	Screw

• COPYRIGHT © 2004 BY DART AEROSPACE LTD. •

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.